



Caution on P2K Installations



Be careful when changing the light bulbs on Proto 2000 locomotives. Don't Let the light wires stick out of the rubber boots causing a short as in the picture above. The arrow points to a short circuit from P2 to P1. This will cause immediate failure of the decoder.

Caution on P2K Installations



Be careful when changing the light bulbs on Proto 2000 locomotives. Don't Let the light wires stick out of the rubber boots causing a short as in the picture above. The arrow points to a short circuit from P2 to P1. This will cause immediate failure of the decoder.